

Railroad Commission of Texas

SURFACE MINING AND RECLAMATION DIVISION

February 24, 2010

Mr. Josh Leftwich Environmental Manager Uranium Energy Corporation (UEC) 400 Mann Street, Suite 900 Corpus Christi, Texas 78401

RE: Weesatche Project, Goliad County

Uranium Exploration Permit No. 123C

Inspection Report

Dear Mr. Leftwich:

Enclosed is a copy of the report for the inspection completed on February 23, 2010, at UEC's Weesatche Project, Goliad County.

If you have any questions, please contact me at (512) 305-8813.

Sincerely,

Mark Schlimgen, Manager

Inspection and Enforcement

MS/sdj Enclosure



RAILROAD COMMISSION OF TEXAS SURFACE MINING AND RECLAMATION DIVISION

URANIUM EXPLORATION INSPECTION REPORT

Project Name: Weesatche				Permit Number: 123C		
Permittee:	UEC			County: Goliad		
Industry Repre	esentative(s) Present:	James Gale			*	
Inspector:	Steve Meadows			Date of Inspection:	February 2	3, 2010
	i e				-	
I. Field Cond	litions and Data Coll	ection	et a			
Samples Colle	cted: No 🛛 Yes	Sa Sa	ample Type:	Water	Soil 🗌	Vegetation
Average Temperature	Soil Condition	nMoist	Date Last Rainfall		nd Direction/ elocity (Est.)	North at 20
Photographs A	ttached: No 🗌 Yes 🗵	(Complete Sec	tion IV)			
			ē			
II. Enforceme	ent Action Taken					
Notice of Viola	ation Issued:	No 🛛	Yes 🗌	NOV No.		
Cessation Orde	er Issued:	No 🖂	Yes 🗌	CO No.		
				/		
1	Her Meadows	02/23/2010		ah Still	war.	2/23/20
Inspector Signature		Date	Revi	ewing Supervisor Sign	natore	Date /

The Railroad Commission of Texas complies with Federal and State laws applicable to race, religion, national origin, sex, and disability. Information is available upon request by calling (512) 463-7288 or 1-800-735-2989 if special assistance is required.

Project Name: Permit Number: Weesatche

123C

Inspection Date:

February 23, 2010

III. Comments - Inspection Narrative

- · Document the area of the permit inspected
- · Discuss observations made during the inspection
- · Document the results of any field tests taken
- Provide a summary of any discussions with industry representatives, along with results, and expectations from those discussions
- · Describe any enforcement action taken during the inspection, along with facts or evidence supporting the enforcement action

No exploration drilling is currently in progress at UEC Permit No. 123C. During this inspection, the 33100 area of exploration was inspected for site restoration issues. On 9-17-08, 32 exploration boreholes were inspected for compliance with the regulation and permit requirements on this property, also referred to as the Gram lease. At this time, muddy conditions prevented access to the lower portions of the 33100 area; however a selection of drilling locations were inspected on higher ground and no significant restoration issues were noted. The general appearance and typical examples of site restoration efforts in the 33100 area of operation are documented in Photos 1-5.

Incidents of mud pit subsidence noted in the P-107 Jacobs area in last month's inspection report have been repaired as seen in Photos 6-7. Site restoration follow up in other areas of UEC Permit No. 123C will be the subject of future inspections.

Project Name: Permit Number:

Weesatche

123C

Inspection Date: February 23, 2010



Photo 1: Exploration area 33100 in UEC Permit No. 123C.



Photo 2: Exploration borehole 33100-13 on 9-17-08.

Project Name: Permit Number: Weesatche

123C

Inspection Date:

February 23, 2010



Photo 3: Exploration borehole 33100-17 on 4-23-09.



Photo 4: Site restoration at borehole 33100-17 on 2-23-10.

Project Name: Permit Number: **Inspection Date:**

Weesatche

123C

February 23, 2010



Photo 5: Site restoration at 33100 borehole drilling location.



Project Name: Permit Number: Weesatche

123C

Inspection Date: February 23, 2010



Photo 7: P-107 subsidence repair on 2-23-10.